

# APPLICATION DATA SHEET

## BLACKFAST 517 ACID PICKLE HEAVY

USE: Use diluted 9:1

APPLICATION: All Aluminium surfaces will require conditioning before blacking. After treatment in Blackfast 451, the workpiece is immersed in Blackfast 517 for 2-3 minutes, rinsed and returned to Blackfast 451 until an even grey colour is developed. Repeat as necessary followed by immersion in Blackfast 481 for 60 seconds.

TANK MATERIAL Tanks should be made of a suitable polypropylene.

PRODUCT SAFETY DATA SHEET: A safety data sheet is available.

Blackfast 517 is part of the Blackfast range of products for the treatment of iron, steel and aluminium at low temperatures.

Blackfast Chemicals continues to improve the quality and performance of its range of products and reserves the right to modify product formulations without prior notice.

AUGUST 2015